

BELZONA REPAIRS CYCLONE INLET

ID: 1171



PROBLEM

The inlet to the pulp cyclone showed severe erosion corrosion after only 8 months of service. It had already been patched once and had holed through again.

APPLICATION SITUATION

The pulp cyclone removes scrap metal, stones, glass and other heavy abrasive debris from the pulp prior to screening.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-11.

A polycarbonate flange form was bolted on the casting and Belzona® 1812 applied to fill the eroded shell and rebuild the damaged flange area. The interior was coated with Belzona® 1321 to provide a smooth the surface and the flange form was removed.

BELZONA FACTS

A replacement fitting was quoted at \$25,000 and six weeks delivery. The Belzona material used in this repair cost less than \$2,000. When the fitting currently in use is replaced by this fitting, it too will be repaired with Belzona abrasion resistant lining. The mill thus has a low cost durable back-up part ready for service.

INDUSTRY

Pulp & Paper

LOCATION

Paper Mill, Michigan U.S.A.

APPLICATION DATE

October 2008

PRODUCTS

Belzona 1812 (Ceramic Carbide FP) Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. The fitting in the repair area
2. Flange form installed. Internal damage evident
3. Belzona 1321 being applied over the Belzona 1812
4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

**BELZONA**