

BELZONA REPAIRS OIL LEAK ON TRANSFORMER FIN

ID: 1483



PROBLEM

Oil leaking from fins

APPLICATION SITUATION

Oil cooled electrical transformer

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

The costly need to drain down the oil to effect a repair was eradicated. The Belzona repair was carried out in less than 2 hours and has proven to be totally successful.

INDUSTRY

Power

LOCATION

Electricity Distribution Co. UK

APPLICATION DATE

2008

PRODUCTS

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the transformer
2. Close up of oil leak area
3. Completed application. Leak sealed with Belzona 1161

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

