

BELZONA REPAIRS LEAKING FLANGE CONNECTION ON TRANSFORMER

ID: 1484



PROBLEM

Oil leaking from flanged pipe connections

APPLICATION SITUATION

Oil filled Transformer

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a.

BELZONA FACTS

Repairs were carried out in-situ without the need to take the transformer off-line. Belzona® 1161 was applied without having to drain the transformer oil. Repair was total success.

INDUSTRY

Power

LOCATION

Electricity Distribution Company, UK

APPLICATION DATE

2006

PRODUCTS

Belzona 1161 (Super UW metal)

SUBSTRATE

Steel

PHOTOS

1. Oil leaking from flange
2. Belzona 1161 being applied
3. Inspection of Belzona 1161 application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

