

BELZONA PUMP REPAIR PROVIDES OVER TEN YEARS OF UNINTERRUPTED SERVICE

ID: 26



PROBLEM

Pump suffered from erosion/corrosion and was completely destroyed after four years of operation

APPLICATION SITUATION

Primary fan pump

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflets CEP-1, CEP-2 and CEP-3.

BELZONA FACTS

Pump replacement cost is \$60,000.00. Cost of Belzona repair: \$9,300.00. After more than ten years of uninterrupted service, the pump is still in use and twice required only minor touch-ups. An impressive savings of three pump replacements.

INDUSTRY

Pulp & Paper

LOCATION

Paper Company in Georgia

APPLICATION DATE

November 1986

PRODUCTS

Belzona 1311 (Ceramic R Metal)

Belzona 1321 (Ceramic S Metal)

SUBSTRATE

Cast iron

PHOTOS

1. Severe damage
2. The wear ring seats rebuilt, clamps help ensure proper alignment
3. Belzona 1321 (Ceramic S Metal) coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

