

BELZONA SEALS TRANSFORMER LID FLANGE

ID: 3091



PROBLEM

Most of the gasket had failed around the 10m perimeter of the lid, with oil seeping down the sides and going to ground. Unfortunately it was not possible to drain the oil below the gasket level and so the application had to be pursued as a live leak with a 1m head pressure.

APPLICATION SITUATION

Lid gasket flange on this 66-11Kv transformer.

APPLICATION METHOD

Application was carried out using Belzona Know-How System Leaflet VPF-11 as a guide. Area of flange and bolts were pressure cleaned and grit blasted. Live leaks stemmed with Belzona® 1291 and Belzona® 1221. Bolt heads top and bottom were encapsulated with Belzona® 1161. Belzona® 1161 and Belzona® 9341 used to create a reinforced band around the flange. Finally over coated with Belzona® 5831.

BELZONA FACTS

The customer was desperate for a fast solution to the problem and whilst there were a couple of very minor leaks still on completion, these were deemed to be well within acceptable limits. The customer was delighted with the results and is looking to repeat the application to other transformers on their site.

INDUSTRY

Power

LOCATION

Gas Distributor, UK

APPLICATION DATE

2011

PRODUCTS

Belzona 1291 (ES Metal)
Belzona 1221 (Super E Metal)
Belzona 1161 (Super UW Metal)
Belzona 5831 (ST Barrier)

SUBSTRATE

Carbon Steel

PHOTOS

1. Original condition of flange with header tank at rear
2. Encapsulation of bolts with Belzona 1161
3. Completed repair close up
4. Finished work after 3 days

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

