

BELZONA STOPS PREMATURE WEAR ON THIS RUBBER BELT

ID: 313



PROBLEM

Gravel from the quarrying operation was wearing the clips out prematurely and creating unscheduled outages.

APPLICATION SITUATION

Conveyor belt clips from a dredger.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-4.

BELZONA FACTS

The repair was not put on too thick because of scraper arm concerns and flapping over the drive roller.

INDUSTRY

Mining & Quarrying

LOCATION

Quarry in Minnesota

APPLICATION DATE

July 2000

PRODUCTS

Belzona 2211 (MP Hi-Build)

SUBSTRATE

Rubber

PHOTOS

View of conveyor belt from dredger
Grinding down edges of new clips
Conditioning repair area with Belzona 2911 (QD Conditioner) Application of Belzona 2211 (MP Hi-Build)

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

