

REBUILDING DAMAGED OVERHEAD CONCRETE

ID: 3823



PROBLEM

Due to the existence of crack in the concrete structure and ingress of water in the cracks, some area of concrete gets part and the round bars are corroded with expose to water and air.

APPLICATION SITUATION

Overhead concrete structure

APPLICATION METHOD

Application carried out in accordance with the Belzona Know-How system leaflet RPA-2 and the selected Belzona 4141 mixed and applied in accordance with the relevant Instruction For Use. Overhead concrete structure has extensive areas of damage created by crack and water leakage and affects the round bars. Application of Belzona 4141 as a lightweight repair system, would protect round bar and reinforce the cracks.

BELZONA FACTS

Belzona 4141 as a solvent free material easily bond to the older concrete surfaces.

INDUSTRY

Mining & Quarrying

LOCATION

Iron Ore Company, IRAN

APPLICATION DATE

July 2012

PRODUCTS

Belzona 4911 (Conditioner)
Belzona 4141 (Magma-Build)

SUBSTRATE

concrete

PHOTOS

1. Removing damaged concrete
2. Damaged area and showing round bars
3. and 4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

