

BELZONA REPAIRS FUELING HOSES

ID: 39



PROBLEM

Bunkering hose outer skin damaged, potentially weakening the hose. A rupture could be catastrophic in terms of the environment and safety.

APPLICATION SITUATION

Bunkering (fueling) hoses

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet SOS-12.

BELZONA FACTS

Replacement cost of the hose section would have been \$5000. Belzona repair cost only \$200.

INDUSTRY

Marine

LOCATION

Ship bunkering (fueling) company, U.S.A.

APPLICATION DATE

March 1999

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2911 (QD Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Damaged section removed
2. Damaged area after conditioning
3. Applying Belzona 2211 (MP Hi-Build Elastomer)
4. Finished application is ready for service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

