

CUSTOMER GOES NUTS OVER BELZONA FLOOR REPAIRS

ID: 394



PROBLEM

Epoxy overlay of concrete floor in processing plant was disbonded in many places.

APPLICATION SITUATION

Factory Floor

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The floor was soaked with pecan oil making the application very difficult. A detergent wash was used on the floor followed by an odorless degreaser followed by mechanical abrasion. This was followed by another degreasing. The pecan factory was so pleased with these initial repairs that they purchased additional material and continue to address other floor problem areas as they arise. After several years all repairs are holding up very well.

INDUSTRY

General Industry

LOCATION

Pecan Processing facility in Las Cruces, New Mexico U.S.A.

APPLICATION DATE

November 2001

PRODUCTS

Belzona 4131 (Magma-Screed)

SUBSTRATE

Concrete

PHOTOS

1. Cleaning.
2. Surface preparation.
3. Application.
4. Finished.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

