

BELZONA REPAIRS TO FLOATING HOSE

ID: 396



PROBLEM

Extensive damage to the rubber flotation.

APPLICATION SITUATION

24" Yokohama floating hose.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Inspected February 2000 hose still in good condition. Repair cost \$3,000; new hose cost about \$70,000.

INDUSTRY

Oil & Gas

LOCATION

Oil Company

APPLICATION DATE

December 1998

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 2221 (MP Fluid Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. The extent of the damage clearly evident.
2. Application of Belzona 2221.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

