

DAMAGED FENDER REFURBISHED USING BELZONA ELASTOMER

ID: 397



PROBLEM

Severe damage to the surface of fenders. In particular securing chains had damaged the rubber covers through constant abrasion.

APPLICATION SITUATION

Fenders used in docking of large ships.

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Due to their size the ability to make repairs on site quickly with Belzona Elastomers was a major benefit.

INDUSTRY

Oil & Gas

LOCATION

Offshore Oil Supply Ship Terminal,
Indonesia

APPLICATION DATE

1991

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged rubber being removed.
2. Application of Belzona Conditioner.
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.