

BELZONA REPAIRS BALL MILL SHELL

ID: 4025



PROBLEM

Due to the nature of the operation, the internal surfaces of the ball mill are subject to constant impact from the falling balls and other media present inside. Shell wall became damaged beneath the wear plates.

APPLICATION SITUATION

Ball mill shell damaged beneath wear plates.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-7. After surface preparation, Belzona 1311 was used to rebuild the damaged areas to restore the original dimensions.

BELZONA FACTS

This application was carried out with minimal downtime, therefore saving money as well as time. The high adhesion and compressive strength of Belzona provides a solid foundation for the wear plates, ensuring a long service life for the mill.

INDUSTRY

Mining & Quarrying

LOCATION

Cement plant, Al Kawmeya, Egypt

APPLICATION DATE

October 2008

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Damaged ball mill
2. Impact damage
3. Surface after preparation
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

