

RUBBER TRACKS ON MOBILE DRILLING RIG QUICKLY REPAIRED WITH BELZONA

ID: 4683



PROBLEM

Several damaged areas on its rubberized tracks required quick repair to prevent track failure.

APPLICATION SITUATION

Mobile Geotechnical drilling machine operating two shifts per day.

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet SHM-1.

BELZONA FACTS

The only alternative was to remove the machine from the building site to the workshop, which would cause downtime and delay to the operator. Belzona team did the repair within few hours' time and the machine was back in service the same day. Cost savings were significant in comparison to alternative.

INDUSTRY

General Industry

LOCATION

Geotechnical survey company, Croatia

APPLICATION DATE

September, 2013.

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Geo drilling machine on site
2. One of the damaged areas on the tracks
3. Damaged area after surface preparation and Conditioning
4. Application finished.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

