

RUBBER LINER IN SLURRY PUMP REPAIRED WITH BELZONA

ID: 4935



PROBLEM

The rubber liner had suffered local damage resulting in an operational shutdown.

APPLICATION SITUATION

Rubber lined Warman 10/8M slurry pump.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know How System Leaflet SHM-9.

BELZONA FACTS

The costumer was able to run the pump the same day saving shutdown costs of 7 days whilst waiting for new replacement liner.

INDUSTRY

Mining & Quarrying

LOCATION

Quarry, Israel

APPLICATION DATE

February 2014

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged rubber liner
2. The Warman 10/8M pump
3. Damaged area Conditioned with Belzona 2911 (Elastomer QD Conditioner)
4. Rubber liner after application of Belzona 2311

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

