


BELZONA REPAIRS CABLE REINFORCED CONVEYOR BELT

ID: 5184



PROBLEM

Cable stayed belt would develop cracks over a period of time.

APPLICATION SITUATION

Cracked cable stayed belt

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SHM-1

BELZONA FACTS

Because of its rapid set-up time, coupled with its quick development of mechanical strength, Belzona 2311 allowed repairs to be made to the belt during unscheduled or short shut-downs.

INDUSTRY

General Industry

LOCATION

BC, Canada

APPLICATION DATE

August 1996

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. View of preparation in progress
2. Close-up of one of the repair areas
3. Completed application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

