

BELZONA REPAIRS ENGINE BLOCK

ID: 5264



PROBLEM

A hole in the engine block allowed the oil to leak out.

APPLICATION SITUATION

Engine block.

APPLICATION METHOD

After proper surface preparation the application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

A broken connecting rod went through the block. The owner replaced the rod but did not know what to do about the hole. Belzona repaired the hole, solving the problem for the owner.

INDUSTRY

General Industry

LOCATION

Seward, AK, USA

APPLICATION DATE

1981

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. The engine block showing the hole
2. The cracks have been stabilized by drilling the extremities
3. A plate was bonded over the hole using Belzona 1111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

