

BELZONA RESCUES A SNOW PLOW HYDRAULIC PUMP

ID: 5268



PROBLEM

The pump had been repaired with brand X, fell apart after five minutes of use.

APPLICATION SITUATION

Broken pump casing

APPLICATION METHOD

The application was carried out in accordance with Belzona System Leaflet ENC-1 using Reinforcement Sheet to bridge the hole.

BELZONA FACTS

A new pump casing was 5000 miles away and could take two weeks to arrive. Snow does not wait in Alaska.

INDUSTRY

Fluid Flow

LOCATION

Anchorage, Alaska, USA

APPLICATION DATE

1983

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 9341 (Reinforcement Sheet)

SUBSTRATE

Aluminum

PHOTOS

1. Aluminum pump casing showing the remains of Brand X failure
2. Casing prepared with grinding
3. Finished casing ready for service.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

