

BELZONA REPAIRS A CRACKED ENGINE BLOCK

ID: 5366



PROBLEM

Engine block cracked by freezing water.

APPLICATION SITUATION

John Deer engine block.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet ENC-1.

BELZONA FACTS

The only alternative was to replace the block. Instead, \$50.00 of Belzona 1111 was used to solve the problem.

INDUSTRY

General Industry

LOCATION

WA, USA

APPLICATION DATE

1992

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Drilling holes along crack
2. Threading holes
3. Studs installed, grinding surface
4. Reinforced Belzona 1111 applied to seal the crack

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

