

BELZONA REBUILT DAMAGE BOW OF RECREATION BOAT

ID: 5444



PROBLEM

The rivets on the bow that hold the two halves of the aluminum boat shell together would get worn out from the successive beachings.

APPLICATION SITUATION

Sealing bow's halves on the recreation boat

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-1.

BELZONA FACTS

Rebuilding this area with fiber glass lasted only a single season. The Belzona repair material is heading into its 2nd season unscathed.

INDUSTRY

Marine

LOCATION

BC, Canada

APPLICATION DATE

July 2004

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Aluminum

PHOTOS

1. Condition of vessel bow showing failed fiber glass repair.
2. Bow rebuilt to shape with Belzona 1311.
3. Entire repair further protected with 2 coats of Belzona 1321.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

