

BELZONA FLOATING ORANGE HOSE

ID: 55



PROBLEM

Massive, deep cut in the hose.

APPLICATION SITUATION

Floating rail hose

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet SOS-12.

BELZONA FACTS

Replacement of the 45-foot long hose would have cost approximately \$40,000 with long delivery time. The Belzona application cost only \$1,000 saving the customer nearly \$40,000.

INDUSTRY

Oil & Gas

LOCATION

Offshore Oil Port in the Gulf of Mexico, USA

APPLICATION DATE

Ongoing since 1994

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)
Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Rubber

PHOTOS

1. Repair procedure in progress using Belzona 9341 (Reinforcement Tape) and special layering technique.
2. Belzona 2211 (MP Hi-Build Elastomer) almost cured.
3. Floating hose ready to go.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

