

BELZONA SEALS BROKEN SKYLIGHTS

ID: 6297



PROBLEM

Under the influence of the sun skylights had broken around the fastening bolts allowing leakage of water into the rooms below whenever it rained.

APPLICATION SITUATION

Roof above the office space has 4 large skylights.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet RPA-3.

BELZONA FACTS

Repair cost less than half the purchase and replacement costs of new skylights. Inspected in August 2016 repairs still in excellent condition and keeping offices dry.

INDUSTRY

Buildings & Structures

LOCATION

Office building, Bielsko-Biala, Poland

APPLICATION DATE

July 2009

PRODUCTS

Belzona 3111 (Flexible Membrane)

SUBSTRATE

Bitumen

PHOTOS

1. Washing damaged skylights 2. Application of Belzona 3111 onto the Belzona 3911 Conditioner 3. Rooftop view immediately after the repair. 4. Rooftop view August 2016

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.