

BELZONA SAVES CAST IMPELLER FROM SCRAP

ID: 6423



PROBLEM

Set of cracks on one side of the newly cast impeller. The end-user had refused to accept the impeller without elimination of the cracked area. After mutual agreement between the customer and end-user, they agreed that a Belzona solution could be used.

APPLICATION SITUATION

New cast iron impeller slurry pump

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet CEP-6. All cracks were terminated, then Belzona 1311 was applied on the cracked area with reinforcement tape. More Belzona 1311 were added to restore the original profile of the impeller and give a smooth finish.

BELZONA FACTS

The customer had no alternatives except to recast the defective impeller, costing a lot of money and time. The conventional repair by welding was not an option because of unpredictable effects. The customer and end-user had previous experience with Belzona for similar applications with reliable results.

INDUSTRY

General Industry

LOCATION

Mechanical Workshop, Bulgaria

APPLICATION DATE

March, 2016

PRODUCTS

Belzona 1311 (Ceramic R-Metal)

SUBSTRATE

Cast Iron

PHOTOS

1. Impeller before application
2. Mechanical grinding and machining of cracked area
3. Masking of the repair area
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

