

BELZONA REPAIR TO LARGE EXCAVATOR CONTROL CABLE

ID: 662



PROBLEM

Torn cable cover due to weather influences and friction with ground. There was need for material which is elastic, has good adhesion, abrasion and water resistance.

APPLICATION SITUATION

Control cable from large iron ore excavator.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-10. Belzona® 9341 (Reinforcement tape) was used between two layers of Belzona® 2311

BELZONA FACTS

Mechanical bonded rubber coupling had been used before on damaged insulation of the cable, but Belzona® 2311 showed better elasticity, adhesion and abrasion resistance. This application have been done on ten further locations.

INDUSTRY

General Industry

LOCATION

Ferro-nickel plant in Macedonia

APPLICATION DATE

June 2003

PRODUCTS

Belzona 2311 (SR-Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. View of excavator
2. Torn cable cover
3. Repaired cable with Belzona 2311
4. Condition after 14 months in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA®

Copyright © 1952-2026 Belzona International Limited.