

BELZONA RENEWS DEFORMED CONVEYOR DRIVE DRUM

ID: 663



PROBLEM

The drive drum had a 15 mm rubber cover. The surface of the drum was mechanically deformed during transportation with fork lift truck.

APPLICATION SITUATION

Rubber clad conveyor drive drum.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

This was the only solution for rebuilding the deformed drum surface. The success of the repair lead to similar applications carried out on two more conveyor belt drums.

INDUSTRY

Mining & Quarrying

LOCATION

Coal mine in Macedonia

APPLICATION DATE

August 2002

PRODUCTS

Belzona 2211 (MP Hi Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

View of the damaged drum Preparing the deformed area Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

