

BELZONA REBUILDS THE UNDERSIDE OF PULPMILL FLOOR

ID: 685



PROBLEM

Moisture, vibration and impact from above had caused the underside of this concrete deck to spall badly leaving exposed corroding rebar.

APPLICATION SITUATION

Badly damaged underside of concrete floor

APPLICATION METHOD

Application carried out using a modified version of Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

Using Belzona 4141 Magma Build allowed the underside of the floor to be rebuilt in a single application without the need for forms saving many additional hours of downtime when compared with a conventional repair (Footnote: The damaged sections on the top side of the deck were rebuilt in 2002 with Belzona 4111 Magma Quartz and the complete deck area sealed with Belzona 5122 (Clear Cladding).

INDUSTRY

Pulp & Paper

LOCATION

Pulp & Paper Operation, BC, Canada

APPLICATION DATE

June 2003

PRODUCTS

Belzona 4141 (Magma Build)

SUBSTRATE

Concrete and steel reinforcement bars

PHOTOS

1. View of corroded rebar and spalled concrete underside
2. A partially completed underside showing the unfinished section after grit blasting to remove all corrosion from the rebar
3. Application in final stages of completion

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

