

BELZONA REPAIRS A FLOATING HOSE

ID: 7511



PROBLEM

The rubber reinforced covers and flotation/insulation on fuel hoses was damaged. Thought to be caused by the ships propeller during fuel loading and unloading.

APPLICATION SITUATION

Fuel transport hoses offshore

APPLICATION METHOD

The repair was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

The application was completed at a fraction of the cost of a replacement hose. The customer wanted to use Belzona because previous applications had surpassed life expectancy expectations.

INDUSTRY

Oil & Gas

LOCATION

Holyhead, Wales

APPLICATION DATE

July 2017

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Damaged rubber.
2. Surface preparation.
3. Application in progress.
4. Finished application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

