

LORRY ENGINE REPAIRED WITH BELZONA

ID: 7576



PROBLEM

Cracked block due to freezing over winter months.

APPLICATION SITUATION

Lorry engine.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC- 1

BELZONA FACTS

Welding of this damage would take a long time and potentially cause more damage so repairing with Belzona 1111 was much better for customer.

INDUSTRY

Transport

LOCATION

Transport company, Slovakia

APPLICATION DATE

2014

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast iron

PHOTOS

1. Cracked engine
2. Crack detection to identify all cracks
3. Surface preparation
4. Belzona 1111 repair incorporating Belzona 9341 Reinforcement Tape.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

