

BELZONA REPAIRS JOINTS IN CONCRETE

ID: 7615



PROBLEM

Heavy fork lift truck traffic destroyed joint nosings.

APPLICATION SITUATION

dilatation (contraction) joints in concrete floor.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet FPA-5 and FPA-6.

BELZONA FACTS

Customer tried to repair damaged joints several times with another product but after 2 weeks problem returned. After Belzona repair customer has no problem.

INDUSTRY

General Industry

LOCATION

Furniture production plant, Slovakia,

APPLICATION DATE

2015

PRODUCTS

Belzona 4111 (Magma Quartz)

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Concrete

PHOTOS

1. Damaged dilatation joint
2. Repair in progress
3. Belzona 2211 application
4. Joints ready for work

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

