

BELZONA SUPERWRAP REPAIRS OFFSHORE PIPES

ID: 7634



PROBLEM

External Corrosion caused damage to the pipe, they also wanted to seal the thread-o-lets, which were no longer required. The repair had to be compliant to ASME PCC-2 and no hot work was permitted.

APPLICATION SITUATION

Offshore Platform

APPLICATION METHOD

Application carried out in accordance with a modified version of Belzona System Leaflet VPF-11.

BELZONA FACTS

The majority of the large diameter pipe was in a good condition so a patch was just more practical and economical than a replacement.

INDUSTRY

Oil & Gas

LOCATION

Texas, USA

APPLICATION DATE

April 2017

PRODUCTS

Belzona SuperWrap II System

SUBSTRATE

Carbon steel

PHOTOS

1. Repair location.
2. Grit blasted surface.
3. Pit filling carried out with Belzona 1111.
4. Finished SuperWrap II repair.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

