

BELZONA SEALS COOLER SHELL

ID: 767



PROBLEM

Erosion corrosion had caused hole in the shell of the cooler. Location and timescale made replacement impossible.

APPLICATION SITUATION

Main engine cooler

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet HEX-5.

BELZONA FACTS

Due to short period in port Belzona was only way to carry out the repairs on the warship with the cooler in place.

INDUSTRY

Military

LOCATION

Italian Navy

APPLICATION DATE

October 2005

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon Steel

PHOTOS

1. Cooler before repair
2. Application underway
3. Completing the application
4. Close up of the repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

