

BELZONA FORMS THE FACES OF 132 SEA WATER FLANGES

ID: 7879



PROBLEM

A new utility sea water cooling facility was commissioned 1 year ago for this plant. Already, the effects of sea water were leading to crevice corrosion on many diameters of pipe line flanges. This was leading to worn out serrations and severe damages on the seating faces. Existing FBE coating failure inside the spools was due to sea water penetration and pitting corrosion on the edges of spool. Leakages observed through various flange faces / weld seams were leading to intermittent shutdowns.

APPLICATION SITUATION

132 Class 150 – 14inch flange / 24inch / 26inch / 30inch / 40inch & 48inch pipe line flanges operating at 7 – 8 bar

APPLICATION METHOD

The flanges were formed in accordance with VPF-17.

BELZONA FACTS

The customer has been using Belzona solutions for various maintenance problems before being introduced to flange face forming during a technical presentation. They then first used the “Flange face forming technique” in December 2017 for 25 48-inch and 40-inch flange faces. Due to the successful performance of Belzona formed flanges, the plant specified Belzona forming technique for all 132 damaged flanges during their recent shutdown in November 2018. Competitors tried to copy the forming technique but were ultimately unsuccessful .

INDUSTRY

Chemical & Petrochemical

LOCATION

Petrochemical Plant, Saudi Arabia

APPLICATION DATE

2018

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1391T

SUBSTRATE

Steel

PHOTOS

1. Sea water leaking through the flanges
2. Flange damage on the edges
3. Application of Belzona 1111 (Super Metal) on the flange to form peaks
4. 48 inch completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

