

IMPELLER REFURBISHMENT COMPLETED BY BELZONA

ID: 8272



PROBLEM

The impeller had eroded over time and now required re-profiling and a protective coating to protect the surface from the potential erosion in the future.

APPLICATION SITUATION

Eroded pump impeller.

APPLICATION METHOD

The substrate was prepared by conventional grit blasting to a minimum surface profile of 75µm and a surface cleanliness of SA 2½. The damaged areas were then rebuilt and re-profiled back to original using Belzona 1111. Once rebuilt, two coats of our Belzona 1391T were applied in accordance with Belzona Know-How System leaflet CEP-03.

BELZONA FACTS

The refurbishment was completed in one day by applications team Belzona. They were the first choice for this repair application due to their strategically situated workshops across the UK, direct access to Belzona materials and a highly trained team of Applicators and Coating Inspectors.

INDUSTRY

Fluid Flow

LOCATION

Pump Engineering Company, Yorkshire, UK

APPLICATION DATE

January 2020

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1391T

SUBSTRATE

Non-Ferrous Metal

PHOTOS

1. Rebuild in progress to blasted impeller
2. Impeller rebuild completed
3. First coat of Belzona 1391T completed
4. Completed Belzona repair and protection application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®