

BELZONA REPAIR OF FLOATING HOSES

ID: 836



PROBLEM

Rubber covers and flotation/insulation on fuel hoses was damaged by ships propeller during fuel loading and unloading.

APPLICATION SITUATION

Fuel transport hoses offshore

APPLICATION METHOD

The repair was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Belzona is the recommended repair option for such repairs. Replacement too expensive and delays unacceptable.

INDUSTRY

Oil & Gas

LOCATION

Oil Refinery, Philippines

APPLICATION DATE

March 2007

PRODUCTS

Belzona 2111 (D&A Hi-Build Elastomer)
Belzona 2131 (D&A Fluid Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Typical damage
2. New insulation being bonded in with Belzona
3. Final outer cover build-up and coating
4. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

