

REPAIR OF DAMAGED PUMP PARTS

ID: 9013



PROBLEM

The pump part was heavily corroded and eroded and not in a condition to use

APPLICATION SITUATION

Customer was unable to find a replacement part and was in a situation not getting the part from manufacturer because of the outdated design.

APPLICATION METHOD

The application was completed in accordance with Belzona System Leaflets CEP 01, CEP 03 and CEP 05

BELZONA FACTS

It saved the down time and helped the customer not to replace the entire equipment due to the unavailability of old design from the manufacturer

INDUSTRY

Oil & Gas

LOCATION

Jubail

APPLICATION DATE

November 2022

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5821

SUBSTRATE

Carbon steel

PHOTOS

1. Initial condition
2. Initial Condition
3. After repair with Belzona 1111
4. After coating with Belzona 5821

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

