

FLANGE REBUILDING AT A FERTILIZER PLANT

ID: 9156



PROBLEM

There was evidence of bimetallic corrosion and erosion in the 24" elbow between the flange and the seal, which was perforated and thinned the thickness of the flange.

APPLICATION SITUATION

Minimum surface preparation to apply Belzona 1161 was key to save time and money.

APPLICATION METHOD

A thin layer of Belzona 1161 was rubbed over the entire damaged surface, then Belzona 1111 was applied to recover thickness and fill the holes produced by erosion.

To maintain the diameter of the holes through which the bolts pass, it was necessary to cut some tubes to be used as molds and thus maintain the original measurements.

BELZONA FACTS

Quick and localized repairs were carried out with Belzona putting the equipment back into service as soon as possible.

INDUSTRY

Chemical & Petrochemical

LOCATION

Barranquilla, Colombia

APPLICATION DATE

May 2017

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1161 (Super UW-Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. View of damage to the flange
2. Surface preparation.
3. Final application.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

