

AUTOMOTIVE ENGINE BLOCK REPAIR

ID: 9538



PROBLEM

Cooling liquid leakage from engine block, on an Opel Astra J model, A14XER engine type.

APPLICATION SITUATION

The customer reported losing engine coolant liquid. The engine block leak's primary cause was identified by the workshop.

APPLICATION METHOD

Workshop cleaned and abraded the surface.

BELZONA FACTS

Belzona offered the local workshop a feasible solution for their client. The traditional repair method would be the engine replacement with a cost of about 3000 euros.

INDUSTRY

Transport

LOCATION

Greece

APPLICATION DATE

September 2024

PRODUCTS

Belzona 1212

SUBSTRATE

Aluminum

PHOTOS

1. Initial condition with prepared surface
2. Start of application
3. Super Metal Application
4. Repair completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

