

OIL COOLER REPAIR AND PROTECTION

ID: 9615



PROBLEM

Due to severe corrosion and erosion, the tube sheet and lid were damaged.

APPLICATION SITUATION

The oil cooler used for many years became inefficient due to damage.

APPLICATION METHOD

Surface blasting to the required Sa 2.5 standard with a minimum 75 µm profile. Plugging the ends of coolers with cork plugs. Filling the tube sheet and cover of the cooler with Belzona 1111 Super Metal. Drilling out the plugs + blasting. Application of Belzona 1341 (2 x) in a total thickness of 500 µm.

BELZONA FACTS

The repair was done quickly, professionally and with high quality, which the customer appreciated with further orders.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Slovakia

APPLICATION DATE

July 2018

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Carbon steel

PHOTOS

1. Heavily damaged exchanger cover
2. The repair was done using cork plugs.
3. Repaired and protected cover.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.