

# SEA WATER PUMP HOUSE PIPE REPAIR

ID: 9812



## PROBLEM

Severe erosion - through wall defect

## APPLICATION SITUATION

Due to the confined space, there were few options available. The flange adapter also could not be easily replaced, leading to lengthy delays and increased downtime. The Distributor UK offered the ideal solution to repair the through wall defect and return structural integrity to corroded pipe.

## APPLICATION METHOD

The through wall defect area was cleaned and prepared to minimum surface profile using power tools. A pre-made plate was bonded using Belzona 1111, the surrounding surface of the pipe was then wrapped with Belzona 1111 incorporating Belzona 9341 to completely cover areas of pipe susceptible to corrosion.

## BELZONA FACTS

Belzona saved on cost of lengthy shutdowns, waiting for replacement components and also reduced on longer downtimes with an in-situ application

## INDUSTRY

Power

## LOCATION

Barrow

## APPLICATION DATE

April 2025

## PRODUCTS

Belzona 1111 (Super Metal)

## SUBSTRATE

Stainless-steel

## PHOTOS

1. Through wall defect on pipe due to severe corrosion
2. Surface area was prepared to minimum surface profile using power tools
3. Plate is bonded over the defect area and clamped in place
4. The entire area is wrapped with Belzona 1111 and Belzona 9341

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

