

PARTY SUPPLIER IN NEED OF BELZONA

ID: 10155



PROBLEM

The surface of the concrete floor had become damaged due to heavy forklifts traffic and impact from heavy pallets being loaded and unloaded. The uneven surface was making it increasingly difficult for the the safe operation of their busy schedule.

APPLICATION SITUATION

The company operation extremely ineffective. Belzona relative rapid curing, and the quality of the products was the natural option for the project.

APPLICATION METHOD

The application was completed in accordance with Belzona Know-How System Leaflet FPA-1. The concrete ramp was grinded down until safe and sound on concrete was found. The Belzona floor repair system was applied to the damaged area without interruptions.

BELZONA FACTS

Other products were used prior to Belzona and all of them failed. In addition, the minimum downtime to complete the repairs was a deciding factor. Since the application was completed, the Belzona repairs have remained intact.

INDUSTRY

Commercial Facilities

LOCATION

South Florida

APPLICATION DATE

April 2023

PRODUCTS

Belzona 4124 (Bulkfill)
Belzona 4131 (Magma-Screed)
Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Damaged sections of the floor
2. After surface preparation, the area was conditioned with Belzona 4911
3. The area was filled with Belzona 4124 except for the top 1/4 inch
4. Top 1/4 inch was filled with Belzona 4131