

BELZONA RAPID FLOOR REPAIR

ID: 1018



PROBLEM

Hole in floor creating problem for fork lift drivers loading and unloading cardboard for box manufacture.

APPLICATION SITUATION

Concrete floor in production area

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The alternative was to saw cut concrete and pour new concrete. That would be more costly because of labor and down time in the area. It was possible to drive over the Belzona applied in morning that night.

INDUSTRY

General Industry

LOCATION

Box manufacturer, Montgomery, Alabama USA

APPLICATION DATE

January 2007

PRODUCTS

Belzona 4911 (TX Conditioner) Belzona 4131 (Magma Screed)

SUBSTRATE

Concrete

PHOTOS

1. Removed concrete from hole
2. Belzona 4911 being applied
3. & 4. Finished application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

