

BELZONA FLOOR IS UP FOR HOT BATH

ID: 1049



PROBLEM

Existing floor covering badly deteriorated due to regular spills of hot CIP solutions. The dairy is only down from production on Saturday/Sunday.

APPLICATION SITUATION

Dairy floor subject to regular cleaning and sterilization. area contains dip tanks containing hot cleaning CIP (Cleaning In Place) chemicals.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -8. The existing coating was removed with diamond grinders and dust collectors. The floor was repaired with Belzona® 4181, then Belzona® 5891 was applied over the top with a non-slip aggregate on the surface.

BELZONA FACTS

The plant chose Belzona because of its previous successes and the ability to complete within the short break in production.

INDUSTRY

Buildings & Structures

LOCATION

Dairy, Oklahoma

APPLICATION DATE

March, 2008

PRODUCTS

Belzona 4181 (AHR Magma Quartz) Belzona 5891 (HT Immersion Grade)

SUBSTRATE

Brick & Mortar

PHOTOS

1. Old floor
2. Surface preparation
3. Coating the floor
4. The rebuilt and finished floor

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

