

BELZONA SEALS HYDRAULIC LEAK

ID: 1297



PROBLEM

Hydraulic pipe had started to leak causing the fluid to drip onto the electrical circuit panel, causing a shutdown.

APPLICATION SITUATION

Hydraulic system of press for stone products

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. A wrap using the Belzona® 1111 with Belzona® 9341 (Reinforcement Tape) was used to encapsulate the leaking weld.

BELZONA FACTS

Repair was able to stop the leak and get the operating press back up and running in a short amount of time minimizing disruption to production.

INDUSTRY

General Industry

LOCATION

Manufacturer of Stone and Marble Products

APPLICATION DATE

August, 2009

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. Leaking weld joint
2. Surface preparation
3. Completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

