

PUMP DIFFUSER REPAIR SURPASSES ALL EXPECTATIONS WITH BELZONA

ID: 1368



PROBLEM

Efficiency losses and pump breakdown due to severe erosion-corrosion of the single vertical axial flow pump (7090 m³/h). Prior to the Belzona solution, the client had to replace the pump components annually. As a significant local electricity supplier, downtime of this critical equipment caused major problems.

APPLICATION SITUATION

Sea water cooling system pump for a 60 MW turbine.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflets CEP-1, CEP-3 and CEP-4.

BELZONA FACTS

The customer was surprised that the eroded equipment could be repaired and delighted with the vastly improved reliability and performance. The pump casing and suction bell were also coated and protected internally and externally. After 9 years in service, the coating was found to still be in excellent condition.

INDUSTRY

Power

LOCATION

National Electricity Provider, Malta

APPLICATION DATE

May 2000

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Cast Iron

PHOTOS

1. Condition of the pump diffuser after 1 year in service
2. Rebuilding of the vane profiles
3. The finished application
4. Application after 9 years service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

