

BELZONA REBUILDS BEARING PLATES ON VERTICAL BORER

ID: 139



PROBLEM

White metal bearing plates badly worn/scored due to oil starvation. Manufacturer of this unit has ceased trading so replacement part is unobtainable.

APPLICATION SITUATION

Craven 90" dia. Vertical Borer

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet MPT-9.

BELZONA FACTS

The repaired machine now runs quieter and more smoothly, providing a higher standard of finish to machined components.

INDUSTRY

General Industry

LOCATION

Steel Manufacturer Engineering Workshop

APPLICATION DATE

March 1997

PRODUCTS

Belzona 1131

SUBSTRATE

Steel

PHOTOS

1. The problem area - excessive wear to white metal plates.
2. Application of Belzona 1131.
3. Chuck going back into machine to form Belzona 1131.
4. The finished job with oil grooves cut into Belzona 1131.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

