

BELZONA SKYLIGHT WEATHERPROOFING

ID: 187



PROBLEM

Rainwater leakage through skylight

APPLICATION SITUATION

Large entry skylight

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflets RPA-3 and RPA-6.

BELZONA FACTS

The resort was considering replacement of the entire skylight at a cost of \$65,000. The Belzona solution was accomplished for only 8% of the replacement cost.

INDUSTRY

General Industry

LOCATION

Luxury Resort on the Atlantic Coast in Northern Florida, U.S.A.

APPLICATION DATE

June 1998

PRODUCTS

Belzona 3111 (Flexible Membrane)
Belzona 3921 (GSC Surface Conditioner)

SUBSTRATE

Lucite by Dupont and metal gutters.

PHOTOS

1. Water leakage was causing problems to the timbers supporting the structure.
2. Application in progress.
3. The entire 30 x 45 feet of skylight was weatherproofed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

