


BELZONA REPAIRS SUBWAY HANDRAIL

ID: 27



PROBLEM

Due to vandalism, a chunk of rubber was missing from the handrail.

APPLICATION SITUATION

Handrail of escalator at a subway station

APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet SHM-1.

BELZONA FACTS

The repair was completed with \$50.00 of Belzona product. The alternative was hot vulcanizing which would have shut the escalator down for one day and cost approximately \$2,000. The repair took only two hours to perform, and after three years, is still in operation today.

INDUSTRY

General Industry

LOCATION

Subway Station in Quebec, Canada

APPLICATION DATE

March 1993

PRODUCTS

Belzona 2311 (SR-Elastomer)

SUBSTRATE

Rubber and nylon fabric

PHOTOS

1. The damage due to the vandalism
2. Application of Belzona 2311 (SR-Elastomer) in progress
3. The finished repair ready for operation

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

