

BELZONA REPAIRS DAMAGED PRE-HEATER FAN SHAFT

ID: 4024



PROBLEM

The shaft was worn out under the bearing.

APPLICATION SITUATION

Worn shaft

APPLICATION METHOD

This application was carried out in accordance with MPT-2. The shaft can be returned to its original dimensions by using released split formers. These can easily be removed once the product has cured to reveal a perfect finish.

BELZONA FACTS

Conventional repair methods would be very time consuming and would be much more expensive. The Belzona solution however reduces this downtime to a fraction of the time and cost.

INDUSTRY

General Industry

LOCATION

Egypt

APPLICATION DATE

2008

PRODUCTS

Belzona 1111 (Super metal)

SUBSTRATE

Steel

PHOTOS

1. The damaged equipment
2. The damaged area
3. The application before removal of formers
4. The completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

