


BELZONA IN-SITU REPAIR OF SHAFT FROM PRE-HEATER FAN

ID: 426



PROBLEM

Worn shaft due to bearing seizure.

APPLICATION SITUATION

Cement pre-heater fan

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

Long term repair effected without having to dismantle and remove rotating element thus realizing savings in both time and costs.

INDUSTRY

Cement

LOCATION

Cement works in Egypt

APPLICATION DATE

March 2002

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the pre-heater fan housing
2. The damaged shaft
3. The prepared split former
4. Completed application after removing former

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

