

BELZONA FIXES TRIP HAZARD

ID: 4830



PROBLEM

The stone had worn down over the years creating a lip of about 20mm between the stone floor and the adjoining vinyl floor, creating a trip hazard. They required a repair sympathetic to the stone and which would cause minimal disruption to the canteen operations.

APPLICATION SITUATION

Stone floor at threshold to college main canteen servery.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The client had previously used other cementitious repair systems in the past which had failed prematurely. They turned to Belzona after seeing how Belzona 4131 can be used in harsh environments and returned to service quickly. Following a recent revisit two years since the application, the repair remains in excellent condition.

INDUSTRY

Buildings & Structures

LOCATION

College, Lancing, West Sussex, UK

APPLICATION DATE

February 2012

PRODUCTS

Belzona 4131 (Magma-Screed)

SUBSTRATE

Stone

PHOTOS

1. Before application 2. Completed application 3&4. Repair still in good condition following revisit 2 years on

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

