

BELZONA RUBBER LINED VALVE REPAIR

ID: 5086



PROBLEM

Valve sealing surface had deteriorated over the years causing inefficiency in stopping flow of water

APPLICATION SITUATION

Water control valve

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-5

BELZONA FACTS

Belzona repair was cost effective and allowed valve to be quickly returned to service. Fast curing Belzona 2311 was only solution available to the customer in the downtime available.

INDUSTRY

Power

LOCATION

Regional Energy Company, Pancevo, Serbia

APPLICATION DATE

June 2014

PRODUCTS

Belzona 2311 (SR Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Valve damage marked up
2. Prepared surface
3. Belzona 2311 application completed
4. Assembled valve to undergo pressure test

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

